

THE PAINT AND COLOUR EXPERTS

Application

Pure Matt

2% Sheen Flat Matt Finish

Fenwick & Tilbrook Pure Matt emulsion is recommended for plaster walls and ceilings, and can also be applied to internal woodwork, metalwork and masonry.

Bare metal should be treated with a suitable primer, ideally Fenwick & Tilbrook Multipurpose Primer, before applying Fenwick & Tilbrook paint.

PROPERTIES:

- Outstanding durability
- Extraordinary depth of colour
- Ease of application
- Covers up to 10 sq m per litre
- Extremely low odour
- Very low VOC content.

APPLICATION NOTES:

New plaster and porous surfaces:

- 1. The surface must be clean and dry.
- 2. Apply one coat of Pure Matt thinned with water (one part water, nine parts paint).
- 3. Apply two coats of Pure Matt.

Previously painted surfaces:

- 1. Thoroughly wash down and remove all flaking and defective coating.
- 2. Make good any cracks and defects.
- 3. Thoroughly rub down to create a matt surface.

- 4. The surface must be clean and dry.
- 5. For any exposed-to-bare areas, apply one coat of Pure Matt thinned with water (one part water, nine parts paint).
- 6. Apply two coats of Pure Matt.
- 7. Bright or light colours may require additional coats.

DRYING TIMES

Touch dry in around 30 minutes.

Interval between coats c.1 hour.

Based on 23°C ambient temperature, 50% relative humidity, 50 micron dry film thickness (DFT).

Temperature, humidity and thickness of coat will affect drying times.

APPLICATION METHODS

Suitable for application by brush, roller or airless spray.

PRIMING

Fenwick & Tilbrook paints are self priming. However, if a heavily repaired substrate has a variation of porosity and colours, priming is recommended as a first coat to create an even base colour. Prime new, bare and porous surfaces by using one coat of Fenwick & Tilbrook paint thinned with water (one part water, nine parts paint).

CLEAN UP

Remove as much product as possible from brushes and equipment before cleaning with warm water. Do not empty into drains or watercourses. Some local authorities have special facilities for the disposal of waste coatings.

STORAGE AND STABILITY

Store upright in dry conditions above 5°C. Protect from frost. To avoid risk of spillage, always store and transport in a secure, upright position.